


TEL: +61 8 8121 7966

FAX: +61 8 8180 1787

E: [INFO@CRUSHPARTSINTL.COM](mailto:INFO@CRUSHPARTSINTL.COM)

| MANUFACTURER    | MACHINE MODEL | PART NUMBER |
|-----------------|---------------|-------------|
| EXTEC / SANDVIK | C10 / QJ241   | BT3009      |
| EXTEC / SANDVIK | C10 / QJ241   | BT3050      |
| EXTEC / SANDVIK | C10 / QJ241   | BT3055      |
| EXTEC / SANDVIK | C10 / QJ241   | BT3511      |
| EXTEC / SANDVIK | C10 / QJ241   | BT3520      |
| EXTEC / SANDVIK | C10 / QJ241   | BT3521      |
| EXTEC / SANDVIK | C10 / QJ241   | BT3522      |
| EXTEC / SANDVIK | C10 / QJ241   | BT4009      |
| EXTEC / SANDVIK | C10 / QJ241   | BT4505      |
| EXTEC / SANDVIK | C10 / QJ241   | BT5014      |
| EXTEC / SANDVIK | C10 / QJ241   | BT5504      |
| EXTEC / SANDVIK | C10 / QJ241   | BT6006      |
| EXTEC / SANDVIK | C10 / QJ241   | BT8012      |
| EXTEC / SANDVIK | C10 / QJ241   | FAKS22X14   |
| EXTEC / SANDVIK | C10 / QJ241   | FAN42       |
| EXTEC / SANDVIK | C10 / QJ241   | FAN64       |
| EXTEC / SANDVIK | C10 / QJ241   | FD2005      |
| EXTEC / SANDVIK | C10 / QJ241   | H7180000    |
| EXTEC / SANDVIK | C10 / QJ241   | HA99000010  |
| EXTEC / SANDVIK | C10 / QJ241   | HA99000011  |
| EXTEC / SANDVIK | C10 / QJ241   | HA99000012  |
| EXTEC / SANDVIK | C10 / QJ241   | HA99000013  |
| EXTEC / SANDVIK | C10 / QJ241   | HM1019      |
| EXTEC / SANDVIK | C10 / QJ241   | HR1052      |
| EXTEC / SANDVIK | C10 / QJ241   | HR1059      |
| EXTEC / SANDVIK | C10 / QJ241   | HR1062      |
| EXTEC / SANDVIK | C10 / QJ241   | HR2524      |
| EXTEC / SANDVIK | C10 / QJ241   | HV3025      |
| EXTEC / SANDVIK | C10 / QJ241   | HV3518      |
| EXTEC / SANDVIK | C10 / QJ241   | HV8501      |
| EXTEC / SANDVIK | C10 / QJ241   | J1660000    |
| EXTEC / SANDVIK | C10 / QJ241   | J1680000    |
| EXTEC / SANDVIK | C10 / QJ241   | J4210000    |
| EXTEC / SANDVIK | C10 / QJ241   | J4360000    |
| EXTEC / SANDVIK | C10 / QJ241   | J437000     |
| EXTEC / SANDVIK | C10 / QJ241   | J4420000    |
| EXTEC / SANDVIK | C10 / QJ241   | J4430000    |
| EXTEC / SANDVIK | C10 / QJ241   | J4520000    |
| EXTEC / SANDVIK | C10 / QJ241   | J4550000    |
| EXTEC / SANDVIK | C10 / QJ241   | J4560000    |
| EXTEC / SANDVIK | C10 / QJ241   | J4930000    |




TEL: +61 8 8121 7966

FAX: +61 8 8180 1787

E: [INFO@CRUSHPARTSINTL.COM](mailto:INFO@CRUSHPARTSINTL.COM)

| MANUFACTURER    | MACHINE MODEL | PART NUMBER |
|-----------------|---------------|-------------|
| EXTEC / SANDVIK | C10 / QJ241   | J5010000    |
| EXTEC / SANDVIK | C10 / QJ241   | J5040000    |
| EXTEC / SANDVIK | C10 / QJ241   | J5080000    |
| EXTEC / SANDVIK | C10 / QJ241   | J5090000    |
| EXTEC / SANDVIK | C10 / QJ241   | J5180000    |
| EXTEC / SANDVIK | C10 / QJ241   | J5210000    |
| EXTEC / SANDVIK | C10 / QJ241   | J5220000    |
| EXTEC / SANDVIK | C10 / QJ241   | J5230000    |
| EXTEC / SANDVIK | C10 / QJ241   | J5240000    |
| EXTEC / SANDVIK | C10 / QJ241   | J5370000    |
| EXTEC / SANDVIK | C10 / QJ241   | J5380000    |
| EXTEC / SANDVIK | C10 / QJ241   | J5390000    |
| EXTEC / SANDVIK | C10 / QJ241   | J5420000    |
| EXTEC / SANDVIK | C10 / QJ241   | J5520000    |
| EXTEC / SANDVIK | C10 / QJ241   | J5640000    |
| EXTEC / SANDVIK | C10 / QJ241   | J6000000    |
| EXTEC / SANDVIK | C10 / QJ241   | J6010000    |
| EXTEC / SANDVIK | C10 / QJ241   | J6020000    |
| EXTEC / SANDVIK | C10 / QJ241   | J6030000    |
| EXTEC / SANDVIK | C10 / QJ241   | J6040000    |
| EXTEC / SANDVIK | C10 / QJ241   | J6050000    |
| EXTEC / SANDVIK | C10 / QJ241   | J6050200    |
| EXTEC / SANDVIK | C10 / QJ241   | J6060000    |
| EXTEC / SANDVIK | C10 / QJ241   | J6110000    |
| EXTEC / SANDVIK | C10 / QJ241   | J6120000    |
| EXTEC / SANDVIK | C10 / QJ241   | J6130000    |
| EXTEC / SANDVIK | C10 / QJ241   | J6140000    |
| EXTEC / SANDVIK | C10 / QJ241   | J6150000    |
| EXTEC / SANDVIK | C10 / QJ241   | J6160000    |
| EXTEC / SANDVIK | C10 / QJ241   | J6170000    |
| EXTEC / SANDVIK | C10 / QJ241   | J6180000    |
| EXTEC / SANDVIK | C10 / QJ241   | J6190000    |
| EXTEC / SANDVIK | C10 / QJ241   | J6200000    |
| EXTEC / SANDVIK | C10 / QJ241   | J6210000    |
| EXTEC / SANDVIK | C10 / QJ241   | J6220000    |
| EXTEC / SANDVIK | C10 / QJ241   | J6230000    |
| EXTEC / SANDVIK | C10 / QJ241   | J6240000    |
| EXTEC / SANDVIK | C10 / QJ241   | J6250000    |
| EXTEC / SANDVIK | C10 / QJ241   | J6260000    |
| EXTEC / SANDVIK | C10 / QJ241   | J6280000    |
| EXTEC / SANDVIK | C10 / QJ241   | J6290000    |




TEL: +61 8 8121 7966

FAX: +61 8 8180 1787

E: [INFO@CRUSHPARTSINTL.COM](mailto:INFO@CRUSHPARTSINTL.COM)

| MANUFACTURER    | MACHINE MODEL | PART NUMBER |
|-----------------|---------------|-------------|
| EXTEC / SANDVIK | C10 / QJ241   | J6300000    |
| EXTEC / SANDVIK | C10 / QJ241   | J6310000    |
| EXTEC / SANDVIK | C10 / QJ241   | J6320000    |
| EXTEC / SANDVIK | C10 / QJ241   | J6330000    |
| EXTEC / SANDVIK | C10 / QJ241   | J6340000    |
| EXTEC / SANDVIK | C10 / QJ241   | J6350000    |
| EXTEC / SANDVIK | C10 / QJ241   | J6390000    |
| EXTEC / SANDVIK | C10 / QJ241   | J6400000    |
| EXTEC / SANDVIK | C10 / QJ241   | J6410000    |
| EXTEC / SANDVIK | C10 / QJ241   | J6460000    |
| EXTEC / SANDVIK | C10 / QJ241   | J6500000    |
| EXTEC / SANDVIK | C10 / QJ241   | J6510000    |
| EXTEC / SANDVIK | C10 / QJ241   | J6520000    |
| EXTEC / SANDVIK | C10 / QJ241   | J6530000    |
| EXTEC / SANDVIK | C10 / QJ241   | J6540000    |
| EXTEC / SANDVIK | C10 / QJ241   | J6550000    |
| EXTEC / SANDVIK | C10 / QJ241   | J6570000    |
| EXTEC / SANDVIK | C10 / QJ241   | J6580000    |
| EXTEC / SANDVIK | C10 / QJ241   | J6590000    |
| EXTEC / SANDVIK | C10 / QJ241   | J6600000    |
| EXTEC / SANDVIK | C10 / QJ241   | J6610000    |
| EXTEC / SANDVIK | C10 / QJ241   | J6620000    |
| EXTEC / SANDVIK | C10 / QJ241   | J6630000    |
| EXTEC / SANDVIK | C10 / QJ241   | J6640000    |
| EXTEC / SANDVIK | C10 / QJ241   | J6670000    |
| EXTEC / SANDVIK | C10 / QJ241   | J6700000    |
| EXTEC / SANDVIK | C10 / QJ241   | J6710000    |
| EXTEC / SANDVIK | C10 / QJ241   | J6720000    |
| EXTEC / SANDVIK | C10 / QJ241   | J6730000    |
| EXTEC / SANDVIK | C10 / QJ241   | J6740000    |
| EXTEC / SANDVIK | C10 / QJ241   | J6750000    |
| EXTEC / SANDVIK | C10 / QJ241   | J6760000    |
| EXTEC / SANDVIK | C10 / QJ241   | J6770000    |
| EXTEC / SANDVIK | C10 / QJ241   | J6780000    |
| EXTEC / SANDVIK | C10 / QJ241   | J6790000    |
| EXTEC / SANDVIK | C10 / QJ241   | J6800000    |
| EXTEC / SANDVIK | C10 / QJ241   | J6810000    |
| EXTEC / SANDVIK | C10 / QJ241   | J6820000    |
| EXTEC / SANDVIK | C10 / QJ241   | J6830000    |
| EXTEC / SANDVIK | C10 / QJ241   | J6840000    |
| EXTEC / SANDVIK | C10 / QJ241   | J6850000    |



**TEL: +61 8 8121 7966**

**FAX: +61 8 8180 1787**

**E: [INFO@CRUSHPARTSINTL.COM](mailto:INFO@CRUSHPARTSINTL.COM)**

| MANUFACTURER    | MACHINE MODEL | PART NUMBER |
|-----------------|---------------|-------------|
| EXTEC / SANDVIK | C10 / QJ241   | J6860000    |
| EXTEC / SANDVIK | C10 / QJ241   | J6870000    |
| EXTEC / SANDVIK | C10 / QJ241   | J6880000    |
| EXTEC / SANDVIK | C10 / QJ241   | J6890000    |
| EXTEC / SANDVIK | C10 / QJ241   | J6900000    |
| EXTEC / SANDVIK | C10 / QJ241   | J6910000    |
| EXTEC / SANDVIK | C10 / QJ241   | J6920000    |
| EXTEC / SANDVIK | C10 / QJ241   | J6930000    |
| EXTEC / SANDVIK | C10 / QJ241   | J6940000    |
| EXTEC / SANDVIK | C10 / QJ241   | J6980000    |
| EXTEC / SANDVIK | C10 / QJ241   | J8080000    |
| EXTEC / SANDVIK | C10 / QJ241   | J8090000    |
| EXTEC / SANDVIK | C10 / QJ241   | J8500000    |
| EXTEC / SANDVIK | C10 / QJ241   | J8510000    |
| EXTEC / SANDVIK | C10 / QJ241   | J8520000    |
| EXTEC / SANDVIK | C10 / QJ241   | J8530000    |
| EXTEC / SANDVIK | C10 / QJ241   | J8610000    |
| EXTEC / SANDVIK | C10 / QJ241   | RU1150      |